EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	527	(164/4.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2007/11/14 13:32
S2	185	(164/154.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2007/11/14 13:20
S3	49	(164/450.2).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2007/11/14 13:21
S4	5	(("3933044") or ("3101618") or ("3596519") or ("3160009") or ("6091444")).PN.	USPAT	OR	OFF	2007/11/14 13:26
S5	5	("4432286" "4726660" "4969035" "5715328" "5922127").PN. OR ("6091444").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/11/14 13:22
S6	35	("2022440" "2981590" "3101618" "3191035" "3350702" "3430045" "3463007" "3501380" "3596519" "3600947" "3821895").PN. OR ("3933044"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/11/14 13:22
S7	22	("1901209" "2999152" "3101618" "3210546" "3401551" "3451254").PN. OR ("3596519"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/11/14 13:24
S8	2	("3160009").URPN.	USPAT	OR	OFF	2007/11/14 13:24
S9	9	("3101618").URPN.	USPAT	OR	OFF	2007/11/14 13:25
S10	2	(("3303537") or ("6491426")).PN.	USPAT	OR	OFF	2007/11/14 13:26
S11	31	("3745460" "4696578" "4713612" "4840495" "5152607" "5201841" "5211477" "5224775" "5246291" "5251980" "5288147" "5295745" "5302022" "5474385" "5721455" "5785799" "5842788" "6006168" "6039471" "6092926" "6169442" "6198245" "6238086").PN. OR ("6491426") URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/11/14 13:26
S12	16	("3303537").URPN.	USPAT	OR	OFF	2007/11/14 13:27
S13	29148	("164").CLAS.	US-PGPUB; USPAT	OR	OFF	2007/11/14 13:32

EAST Search History

	·			T	·····	Ţ .
S14	16	S13 and (((die near3 cast\$3) or (injection near3 mold\$3)) near50 ((temperature\$1 or thermal) near10 (measur\$6 or detect\$3 or sens\$3))). clm.	US-PGPUB; USPAT	OR	OFF	2007/11/14 13:39
S15	16	S13 and (((die near3 cast\$3) or (injection near3 mold\$3)) near50 ((temperature\$1 or thermal or radiation) near20 (measur\$6 or detect\$3 or sens\$3))).clm.	US-PGPUB; USPAT	OR	OFF	2007/11/14 13:39
S16	150	S13 and (((die near3 cast\$3) or (injection near3 mold\$3) or (mold or die)) near50 ((temperature\$1 or thermal or radiation) near20 (measur\$6 or detect\$3 or sens\$3))). clm.	US-PGPUB; USPAT	OR	OFF	2007/11/14 13:39
S17	4	S13 and (((die near3 cast\$3) or (injection near3 mold\$3) or (mold or die)) near50 ((temperature\$1 or thermal or radiation) near20 (measur\$6 or detect\$3 or sens\$3) near50 (air or blow\$3 or compress\$3))).clm.	US-PGPUB; USPAT	OR	OFF	2007/11/14 13:41
S18	5	S13 and (((die near3 cast\$3) or (injection near3 mold\$3) or (mold or die)) near100 ((temperature\$1 or thermal or radiation) near50 (measur\$6 or detect\$3 or sens\$3 or monitor\$3) near100 (air or blow\$3 or compress\$3))).clm.	US-PGPUB; USPAT	OR	OFF	2007/11/14 13:41
S19	10	S13 and (((die near3 cast\$3) or (injection near3 mold\$3) or (mold or die)) near100 ((temperature\$1 or thermal or radiation) near50 (measur\$6 or detect\$3 or sens\$3 or monitor\$3) near100 (air or blow\$3 or compress\$3 or gas or vapor))). clm.	US-PGPUB; USPAT	OR	OFF	2007/11/14 13:43
S20	94	(((die near3 cast\$3) or (injection near3 mold\$3) or (mold or die)) near100 ((temperature\$1 or thermal or radiation) near50 (measur\$6 or detect\$3 or sens\$3 or monitor\$3) near100 (air or blow\$3 or compress\$3 or gas or vapor))).clm.	US-PGPUB; USPAT	OR	OFF	2007/11/14 13:43

11/14/07 1:50:50 PM C:\Documents and Settings\kkerns\My Documents\EAST\Workspaces\10521466ltaf.wsp Page 2

EAST Search History

S21	67	(((die near3 cast\$3) or (injection near3 mold\$3) or (mold or die)) near50 ((temperature\$1 or thermal or radiation) near10 (measur\$6 or detect\$3 or sens\$3 or monitor\$3) near50 (air or blow\$3 or compress\$3 or gas or vapor))).clm.	US-PGPUB; USPAT	OR	OFF	2007/11/14 13:43
S22	67	(((die near3 cast\$3) or (injection near3 mold\$3) or (mold or die)) near50 ((temperature\$1 or thermal or radiation) near10 (measur\$6 or detect\$3 or sens\$3 or monitor\$3) near50 (air or blow\$3 or compress\$3 or gas))).clm.	US-PGPUB; USPAT	OR	OFF	2007/11/14 13:44